

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	4	"5121820".pn. or "5058716".pn.	USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/11/20 21:12
L2	1	L1 and measur\$2	USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/11/20 21:14
L3	0	l1 and detect\$2 with valve	USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/11/20 21:15
L4	0	l1 and detect\$2 with cycle	USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/11/20 21:15
S1	9	torque near converter with input near2 (speed or rpm or revolution)with difference with valve	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/11/20 14:43
S2	1	(test or testing or inspection or inspect\$2)with (transmission or gearbox)and torque near converter with input near2 (speed or rpm or revolution)with difference with valve.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/11/20 15:13
S3	3	(test or testing or inspection or inspect\$2)with (transmission or gearbox)and torque near converter with difference with valve	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/11/20 14:53
S4	4	"5121820".pn. or "5058716".pn.	USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/11/20 21:12
S5	79	torque near converter with slip\$2 with valve with (transmission or gearbox)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/11/20 15:13
S6	3	S5 and(test or testing or inspection or inspect\$2)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/11/20 15:13